



Department of Energy

Richland Operations Office
P.O. Box 550
Richland, Washington 99352

00-RU-0506

Mr. Philip O. Strawbridge
Transition Manager
BNFL, Inc.
3000 George Washington Way
Richland, Washington 99352

Dear Mr. Strawbridge:

RESCHEDULING CORRECTIVE ACTION ASSESSMENT WITH CORRECTIVE ACTION NOTICE (CAN) CAN-2000-01

- Reference:
- (1) BNFL letter from A. J. Dobson To D. C. Gibbs, RU, "BNFL, Inc. Corrective Action Plan In Response To Corrective Action Notice Can-2000-01," CCN 012568/00-RU-0329, dated April 14, 2000.
 - (2) RU letter from D. C. Gibbs to M. J. Bullock, BNFL, "RU Comments on BNFL Second Response to Authorization Basis Maintenance Inspection Report IR-99-007 and Transmittal of Corrective Action Notice CAN-2000-01," 00-RU-0267, dated March 14, 2000.
 - (3) BNFL letter from A. J. Dobson to D. C. Gibbs, RU, "Request to Reschedule Authorization Basis Corrective Action Activity," CCN 012568/00-RU-0453, dated June 15, 2000.

In Reference 1, BNFL Inc. (BNFL) committed to perform a Quality Assurance (QA) surveillance of BNFL's Authorization Basis maintenance process. The surveillance was to verify the effectiveness of corrective actions taken in response to Reference 2. In Reference 3, BNFL requested to reschedule the QA surveillance. The Regulatory Unit has considered the request and determined that rescheduling the surveillance is acceptable.

Mr. P. O . Strawbridge
00-RU-0506

-2-

Nothing in this letter should be construed as a changing the Contract (DE-AC27-96RL13308). If you have any questions, please contact me or Pat Carier of my staff at 376-3574.

Sincerely,

D. Clark Gibbs, Regulatory Official
Office of Safety Regulation
of the RPP-WTP Contractor

REG:LFM

cc: M. P. DeLozier, CHG
C. Younger, BNFL